

## ***UV-6300PC Spectrophotometer***

<h3><b>Instruction Manual</b></h3>
------------------------------------

**European Catalogue Number:**

**634-6041**

Version: 1.0.2

Issued: 04 April 2014



## Legal Address of Manufacturer

### **Europe**

VWR International Europe bvba

Researchpark Haasrode 2020

Geldenaaksebaan 464

B 3001 Leuven

Tel.: +32 16 385 011

<http://www.be.vwr.com>

Made in China

# Table of Contents

## Part 1: Spectrophotometer

Safety Information .....	3
Package Contents.....	4
Unpacking .....	4
Installation .....	4
Symbols and Conventions .....	5
Specifications .....	5
Overview .....	6
Description of Buttons and Switches.....	6
Operational Keys.....	7
Getting Started .....	9
Important Guidelines .....	10
General Operating Instructions .....	10
Operation .....	11
Basic Mode.....	12
Quantitative Mode .....	13
Wavelength Scan .....	17
Kinetics .....	19
DNA/Protein Mode.....	22
Multi-Wavelength Mode.....	23
System Utility.....	25
Troubleshooting .....	29
Repair and Maintenance .....	30
Daily maintenance .....	30
Check lamp.....	31
Spare Parts Replacement .....	31

Accessories and Spare Parts.....	35
----------------------------------	----

## Part 2: Software

Functions.....	37
Main Functions .....	37
Spectrum processing function .....	38
System check and calibration function .....	38
Installation .....	39
Introduction .....	42
Operation .....	46
Single wavelength photometric measurement.....	46
Fixed point measurement.....	47
Wavelength Scanning.....	52
Time Scanning (Kinetic Analysis).....	64
DNA/Protein Measurement.....	66
Appendix 1 .....	69
Technical service .....	70
Warranty.....	70
Equipment disposal .....	71

# Part 1: Spectrophotometer

## Safety Information

Please follow the guidelines below, and read this manual in its entirety to ensure safe operation of the unit.

VWR issues the following recommendations with regard to the use of the UV-6300PC Spectrophotometer.



- Do not open the device.
- Disconnect the device from the mains supply before carrying out maintenance work or changing the fuses.
- The inside of the device is a high-voltage area.
- Do not use the device if it is damaged, especially if the main power cable is in any way damaged or defective.
- Repairs may only be carried out by the service technicians from your local VWR office and authorized contractual partners.
- The device must be connected to a power outlet that has a protective ground connection.
- If the equipment is used in a manner not specified by the manufacturer, the protection provided by the equipment may be impaired.



- Do not allow any liquid to enter the device.
- Do not operate the device in a hazardous location or potentially explosive environment.

## Package Contents

Description	Quantity
Spectrophotometer	1PC
Glass Cuvette	4PCS
Quartz Cuvette	2PCS
USB Disk	1PC
Power Cord (Euro Plug)	1PC
Power Cord (UK Plug)	1PC
Power Cord (CH Plug)	1PC
USB Cable	1PC
CD-ROM	1PC
Quick Manual	1PC
Instruction Manual	1PC
Dust Cover	1PC

## Unpacking

Open the package and carefully check the enclosed items against the packing list. If any of the items are missing or damaged please contact your local VWR office and authorized contractual partners.

## Installation

### Placement

Place the instrument carefully on a stable surface.

### Install printer (optional)




Check to confirm instrument power switch is turned off, connect the printer's data cable to the instrument's parallel port.

### Link the power cord

Check to confirm the instrument power switch is turned off, and the power cord is plugged into two separate power interfaces and the power supply socket apparatus.

## Symbols and Conventions

The following chart is an illustrated glossary of the symbols that are used in this manual.

	<b>CAUTION</b> This symbol indicates a potential risk and alerts you to proceed with caution
	<b>CAUTION</b> This symbol indicates the presence of high voltage and alerts you to proceed with caution
	<b>CAUTION</b> This symbol indicates risks associated with hot surfaces

## Specifications

<b>Optical System</b>	Double Beam
<b>Wavelength Range</b>	190–1100 nm
<b>Band Width</b>	1 nm
<b>Stray Light</b>	≤0.05%T @ 220 nm & 360 nm
<b>Photometric Range</b>	0 to 200%T,-0.3 to 3.0 A, 0 to 9999 C
<b>Wavelength Accuracy</b>	±0.3 nm
<b>Photometric Accuracy</b>	±0.3%T or ±0.002 A@1A
<b>Baseline</b>	0.001 A (200 to 1000 nm)
<b>Stability</b>	0.001 A/h @ 500 nm
<b>Memory</b>	32K (internal), Unlimited (USB disk)
<b>Language</b>	English, French, German, Spanish
<b>Display</b>	320×240 Dots Matrix LCD
<b>Interface</b>	USB, Parallel
<b>Measuring Procedure</b>	Photometry, Quantitation, Wavelength Scan, Kinetics, DNA/Protein, Multi-wavelength
<b>Power Supply</b>	AC 110/220 V, 50/60 Hz
<b>Dimension</b>	590×420×260 mm
<b>Weight</b>	26 kg
<b>Work Environment</b>	15 to 35 °C, 15 to 70% relative humidity
<b>Store Environment</b>	-10 to 50 °C, 15 to 70% relative humidity

**This instrument is compliant to the European Directives on**

**Low Voltage Directive 2006/95/EC**

**Electromagnetic compatibility 2004/108/EC**

**Restriction on use of Hazardous Substances RoHS 2011/65/EU and their amendments.**

## Overview

UV-6300PC Spectrophotometer used in chemistry, pharmaceuticals, biochemical, metallurgy, light industry, textile, material, environments, medical, education and some other fields for quality control laboratories.

## Description of Buttons and Switches

### Front View




### Rear View






## Operational Keys




Key

Functions




Function keys: Functions on-screen prompts




**Numeric keys:** Enter numbers and letters



**CLEAR key:** Delete the input value or stored data



**ESC key:** Return to previous interface



**100%T/0Abs key:** Blank




**OPEN key:** Open files stored in internal memory



**SAVE key:** Save files to internal memory



**START/STOP key:** Start/Stop testing



**GOTO λ key:** Set wavelength



**PRINT key:** Print measuring result



**ENTER key:** Confirm operation



**CELL key:** Select/Deselect auto-cell holder



**RIGHT, LEFT keys:** Search peak/valley and set X scale




**UP, DOWN keys:** Scroll menu/data and set Y scale

# Getting Started


The following chart describes the basic operation of the instrument.

## Turn on and self-check

Switch on the power. The instrument begins to self-check and perform 15 minutes' warm-up. Self-check includes the following steps:



Turn on lamps → RAM Check → Start RTOS kernel → Initialize Comm. Port → Initialize Printer → Initialize AD → System position → Warm up.



After warm-up, the instrument will ask the user to re-calibrate the system. The user can decide if they need to re-calibrate the system or not. After this step, the instrument is ready to work normally.




## Important Guidelines

- Reagents and dilution buffers can cause cauterization and other damage to health.
- Samples (nucleic acids, proteins, bacteria cultures) can be infectious and cause serious damage to health.
- During sample preparation, measuring procedures and maintenance and cleaning work, observe all local laboratory safety precautions (e.g. wear protective clothing and gloves, use of disinfectant) regarding the handling of sample material.
- Dispose of measuring solutions and cleaning and disinfectant materials in accordance with the relevant local laboratory regulations.



## General Operating Instructions

### Select application



Main menu, press numeric keys or use the ▲, ▼ keys to select the corresponding menu, then press

 to enter.



### Set wavelength

Press  to set wavelength, use numeric keys to input the values, press  to confirm and go to the point you set, then carry out the blank automatically.

### Set parameters

In different application, press function key to set parameters, press ▲, ▼ to choose or input the values by numeric keys, press  to enter into, press  to return.


### Set auto-cell holder

Press  to activate the auto-cell holder and press the relevant numeric key (1–8) to make corresponding cell position at the light path. Press  again to deactivate the auto-cell holder.


### Delete the input value

Press  to delete a character, press  to delete all the characters.


### Delete the test results and stored data

Press  to delete the test result or stored data. If the USB disk was installed, the data will be deleted from the USB disk, otherwise the data will be deleted in the internal memory.

### Blank

Put the reference in the main light path and reference light path, press  to carry out the blank.



### Measure samples

Put the sample in the main light path and reference in the reference light path, press  to measure.





### Print the test results

Press  to print the test results.

### Store the test results

Press  to store the test results, input the file name using the numeric keys and press  to save. If the USB disk was installed, the data will save in the USB disk, otherwise the data will save in the internal memory.

### Load the stored file

In the test interface, press  to go into the file selecting interface, press ,  to select the file you want, press  to open. If the USB disk was installed, the data will open from the USB disk, otherwise the data will open from the internal memory.

## Operation

### Self-check

Remove all the blocks in the light path and close the lid of the compartment. Switch on the power supply to begin the self-test.

### Warm-up

After self-test, the instrument goes into pre-ready state. For accurate test results, at least 30 minutes of warm-up is required.


### Check the cuvettes

The cuvettes must be clear with no remains of previous samples on the surface. Only silicon (quartz) cuvettes are permitted to be used in the range of UV area.



## Basic Mode

### 1. Enter into Basic Mode



Main menu, press numeric key  or ,  to select Basic Mode, then press  to enter.



### 2. Set photometric mode

Press  to set photometric mode. Press ,  to select Abs., T% or Conc./Factor and press  to confirm. If you choose Abs. or T%, please go directly to step 5.

### 3. Set concentration unit

Press  to set concentration unit. Press ,  to choose unit, then press  to confirm. You can also choose Other to input the self-defined unit.

### 4. Set Factor or Standard

There are two possible methods:



#### Method 1: Input Factor F

Press  to set F. Input the value of F using the numeric keypad, press  to confirm. The F value will then be displayed on the screen.

#### Method 2: Standards Mark

Put the reference sample in the light path and calibrate 100%T/0Abs; put the standard sample in the light path, press  to start the mark. Input the concentration value of the standard and press  to confirm; it will then be displayed on the screen.

## 5. Set wavelength

Press  to set the wavelength, input the value by the numeric keypad, then press  to confirm.

## 6. Measurement samples

Put the sample to be measured in the main light path and put reference in the reference light path; the result is then displayed on the screen automatically.

## 7. Print the test results

Press  to print the test results.

Basic Mode Test Report


Wavelength: 500.0nm  
Result: 0.000 Abs  
Date & Time: mm-dd-yyyy, hh:mm:ss

Model: UV-6300PC  
SN: UQEXXXXXXX  
Version: A1.176  
VWR International bvba

## Quantitative Mode

### 1. Enter into Quantitative Mode

Main menu, press  or press ,  to select Quantitative Mode, then press  to confirm.




### 2. Set unit

Press  to set concentration unit, press ,  to select and press  to confirm.












### 3. Set up standard curve or load the stored curves

Press  to enter the setup interface. Two methods are then available.














### Set up standard curve:






#### Method 1: Input regression equation


- 1) **Set Fit Curve method.** Press  to set Fit Curve method, use ,  to choose the method and press  to confirm.
- 2) **Set wavelength.** Press  to set wavelength. Use ,  to choose measure method, then press  to confirm. Input the wavelength value required and press  to confirm.
- 3) **Input the factor of the regression equation.** Press  and input the factors, then press  to confirm.

#### Method 2: Use standard samples

- 1) **Set fit method.** Press  to set fit method, press ,  to choose fit method, then press  to confirm.
- 2) **Set wavelength.** Press  to enter the wavelength setting interface, press ,  to select measure method and press  to confirm. Input the value of the wavelength and press  to confirm.
- 3) **Set up standard samples.** Press  to set up standard, input the concentrations of corresponding standard samples according the indication and press  to confirm. users



can use ,  to select the value that they have just input and press  to delete, then input a new value and press  to confirm. Press  to cancel after all the values have been input.



WL: 500.0nm 10:00:00

Calibration Table

No.	Conc. (mg/ml)	Abs
1	0.000	

C=0.226+1.031\*A+^1 r=0.962

Method Params Standard Show Curve


WL: 500.0nm 10:00:00


Setup Standard Conc.

No.	Conc. (mg/ml)	Abs
1	0.000	
2	1.000	
3	0.000	

C=0.226+1.031\*A+^1 r=0.962

Input Standard Conc.:0.0000\_

- 4) **Calibrate standard samples.** Put the corresponding standard samples in the main light path and the reference in the reference light path as the screen indicates and press  to measure. The Abs value will then appear in the corresponding table.



WL: 500.0nm 10:00:00

Calibration Table

No.	Conc. (mg/ml)	Abs
1	0.000	
2	1.000	
3	2.000	

C=0.226+1.031\*A+^1 r=0.962

Method Params Standard Show Curve

WL: 500.0nm 10:00:00







Calibration Table


No.	Conc. (mg/ml)	Abs
1	0.000	0.102
2	1.000	0.200
3	2.000	0.297

C=0.226+1.031\*A+^1 r=0.999

Method Params Standard Show Curve


### Load the stored curves

In the Calibration Table interface, press  to enter the selected file's interface. Use ,  to select the curve required and press  to load. Users can press  to view the curve or press  to cancel.




### 4. Return the sample measurement interface


In the Calibration Table interface, press  to return to the Quantitative Test interface.



## 5. Measure samples

Place the sample to be tested in the main light path and reference in the reference light path, then press

 to measure. The test result will then be displayed in the data sheet. Repeat this step until all the samples have been measured.



## 6. Print the test results

Press  to print the test results.

## Quantitative Test Report

File Name: Abc

Date & Time: mm-dd-yyyy, hh:mm:ss

No.	500.0nm	Abs(ef)	C(mg/L)
1	0.212	0.212	0.212
2	0.210	0.210	0.210
3	0.209	0.209	0.209

Fitting Params:

$$C=1.000 \cdot A^1$$

$$r=1.000$$

Model: UV-6300PC



SN: UQEXXXXXXX


Version: A1.176

VWR International bvba


## Wavelength Scan

### 1. Enter the wavelength scan interface


Main menu, press numeric key **3 DEF** or ,  to select Wavelength Scan and press **ENTER** to enter.



### 2. Parameters setup

Press  to set parameters, set scan from, scan to, scan step and scan speed, then press **ENTER** to confirm.

### 3. Set photometric mode

Press  to set photometric mode, choose T%, Abs. or E and press **ENTER** to confirm.

### 4. Scan samples




Put the sample to be measured in the main light path and put reference in the reference light path, press

START  
STOP








to scan the sample, or press




ESC

to cancel.




## 5. Search peaks

After scanning, press  to go into peak search mode. Press  to set peak height, input the peak height and press  to confirm. Press ,  to display the value of every wavelength point. Press ,  to display the value of every peak.




## 6. Smooth the curve

After scanning, if there are many burrs visible, press  to smooth the curve.

## 7. Print the test results


After scanning, press  to print the test results.





## Kinetics

### 1. Enter Kinetics Mode



Main menu, press **4 GHI** or **▲, ▼** to select Kinetics Mode and press **ENTER** to confirm.





### 2. Setup parameters

Press  to set parameters, input the corresponding values of Total Time, Delay Time and Time Intervals according the on-screen indications. Press  to confirm.



### 3. Set photometric mode


Press  to set photometric mode, choose T% or Abs. and press  to confirm.

### 4. Set wavelength



Press  to set wavelength, input the value of the wavelength using the numeric keypad and press  to confirm.


### 5. Measure samples

Put the sample to be measured in the main light path and put reference in the reference light path, press  to begin the test, or press  to cancel.







### 6. Calculate response rate

After scanning, users can calculate the response rate of a particular period by pressing  to go into Process interface. Input the values for Begin Time, End Time and Factor separately and press  to confirm. The value of I.U. will then be displayed on the screen.




## 7. Search peaks

After scanning has finished, press  to go into search mode. Press ,  to search the value of every point.



## 8. Print the test results


Press  to print the test results.





## DNA/Protein Mode

## 1. Enter DNA/Protein Mode








Main menu, press **5** **J K L** or ,  to select DNA/Protein Mode and press **ENTER** to confirm.



## 2. Setup parameters

Press  to set coefficients, input all the values of f1 to f4 using the numeric keypad according the on-screen indications and press  to confirm.

### 3. Choose measure method


Press  to set method. Press ,  to choose Absorbance Difference 1 or Absorbance Difference 2, then press  to confirm. If you do not want to measure reference, use ,  to select No, then press  to confirm.

#### 4. Set concentration unit


Press  to set concentration unit. Use ,  to select unit and press  to confirm.

## 5. Measure samples

Put the sample to be measured in the main light path and put reference in the reference light path, press

 to measure. The result will be displayed in the data sheet.





## 6. Print the test results


Press  to print the test results.






## Multi-Wavelength Mode

### 1. Enter Multi-Wavelength Mode

Main menu, press  or , to select Multi-Wavelength Mode and then press  to enter the multi-wavelength measurement interface.




## 2. Set up wavelength


Press  to enter the wavelength setting interface, then input all the wavelength values one by one using the numeric keypad. Press  to confirm, or press  to return.

## 3. Set photometric mode

Press  to set the photometric mode, use ,  to select Abs. or T% mode, press  to confirm.

## 4. Measure samples

Put the sample to be measured in the main light path and put reference in the reference light path, press  to measure, the test result will be displayed in the data table.




WL: 500.0nm 10:00:00		
Multi-Wavelength Test---3 WL D2		
No.	WL (nm)	Abs
	300.0	
	310.0	
	320.0	

WL: 500.0nm 10:00:00		
Multi-Wavelength Test---3 WL D2		
No.	WL (nm)	Abs
1	300.0	1.011
	310.0	1.205
	320.0	0.093

## 5. Print the test results

Press  to print the test results.

**Multi-Wavelength Test Report**


File Name: Abc  
Date & Time: mm-dd-yyyy, hh:mm:ss

Sample---1  
500.0nm 0.251Abs  
510.0nm 0.243Abs

Unit: Abs  
Model: UV-6300PC  
SN: UQEXXXXXXX  
Version: A1.176  
VWR International bvba.

## System Utility

Main menu, press **7 PQRS** or use **▲, ▼** to select System Utility and press **ENTER** to confirm.




## Wavelength Reset

Press **1** or use **▲, ▼** to select Wavelength Reset then press **ENTER** to begin the calibration. Note: During the course of the calibration procedure, opening the lid of the compartment is prohibited.

## Printer Setup

Press **2 ABC** or **▲, ▼** to select Printer Setup then press **ENTER** to confirm.



- **Reset Printer**

Press 1 or use ▲, ▼ to select Reset Printer and press ENTER to confirm. Then the printer will be reset to its initial condition.

- **Select Print Port**

Press 2 ABC or use ▲, ▼ to choose Select Print Port and press ENTER to confirm. Use ▲, ▼ to choose LPT or Comm. and then press ENTER to confirm.

- **Select Printer**


Press 3 DEF or use ▲, ▼ to choose Select Printer and press ENTER to confirm. Use ▲, ▼ to select the printer you wish to print from and then press ENTER to confirm.

- **Change Print Mode**

Press 4 GHI or use ▲, ▼ to select Change Print Mode and press ENTER to confirm. Two modes are available: Print Data Sheet and Print the Display Interface.

## Lamp Service

Press 3 DEF or use ▲, ▼ to select Lamp Service, press ENTER to enter the Lamps Management interface.



- **Switch On/Off D2 lamp**

Press 1 or ▲, ▼ to select Switch On/Off D2, then press ENTER to switch on or switch off the D2 lamp.

- **Reset the usage time of D2 lamp**

Press **2 ABC** or use **▲, ▼** to select "Reset D2 Lamp Usage Time" and press **ENTER**. The D2 lamp's usage time will be displayed and the system will ask for confirmation that you want to reset the usage time. Press **▲, ▼** to select Yes, then press **ENTER** to confirm. The system will record the usage time from zero.

- **Switch On/Off W lamp**

Press **3 DEF** or use **▲, ▼** to select "Switch On/Off W Lamp" and press **ENTER** to switch on or switch off the W lamp.

- **Reset the W lamp usage time**


Press **4 GHI** or use **▲, ▼** to choose "Reset W lamp usage time" and press **ENTER**. The W lamp's usage time will then be displayed and the system will ask for confirmation that you want to reset the usage time. Press **▲, ▼** to select Yes and then press **ENTER** to confirm. The system will record the usage time from zero.

- **Change switch point**



Press **5 JKL** or use **▲, ▼** to choose Change Switch Point and press **ENTER** to confirm. Input the wavelength point value (325–375 nm) and press **ENTER** to confirm.

## Clock Setup


Press **4 GHI** or use **▲, ▼** to select Clock Setup, then press **ENTER** to enter the Clock Management interface.





- **Set time**

Press  or ,  to select Set Time and press  to confirm. Input the time (hour, minute, second) using the numeric keypad, then press  to confirm and return automatically.



- **Set date**

Press  or use ,  to select Set Date and press  to confirm. Input the date (year, month, day) using the numeric keypad, then press  to confirm and return automatically.



- **Display time**

Press  or use ,  to select Display Time and press  to confirm. Then the time will then be displayed in the top right corner.

- **Display date**



Press  or use ,  to select Display Date and press  to confirm. The date will then be displayed in the top right corner.


### Refresh dark current

Press  or use ,  to select Refresh Dark Current and press  to confirm. The system will then begin to refresh the dark current.





**Note:** During this process, opening the lid of the compartment is prohibited.

### Connect to PC








Press  or use ,  to select Connect to PC, and press  to confirm. When the instrument is connected to the PC, it displays “Controlled by PC”.







## Beeper on/off

Press  or use ,  to select Beeper On/Off and press  to switch on or switch off the beeper.






## Language selection

Press  or use ,  to choose Language Selection and press  to enter the language selection interface, press ,  to choose language (English, French, German, Spanish) and press  to confirm. The interface will then change into the selected language.




## Refresh system baseline

Press  or use ,  to select Refresh System Baseline and press  to confirm. The system will then scan the baseline. Note: During this procedure, opening the lid of the compartment is prohibited.

## Delete all saved files

Use ,  to select “Delete All Saved Files” and press  to confirm. The system will ask for confirmation that you want to delete all files. Use ,  to select “Yes”, then all the files in the RAM will be deleted.

## Restore default settings

Use ,  to select Restore Default Settings and press  to confirm. The system will then restore the initial settings.

# Troubleshooting

Review the information in the table below to troubleshoot operating problems.

Problem	Cause	Solution
Power on, no response	Power cord connection is not reliable	Improve connectivity
	Fuse burning	Replace fuse
Measurement uncertainty	Warm-up period not long enough	Continue warm-up for more time

	Glass cuvettes used in UV range	Use quartz cuvettes
	Sample is not stable	Improve the sample
	The concentration of sample is too high	Dilute the sample
	Power supply voltage low or not stable	Improve the power supply
	Lamp damage or lamp life maturity	Replace lamp
Dark current error during self-check	The lid of the compartment is open during self-check	Close the lid, restart
System calibration failed	Something is blocking the light path	Remove it, calibrate again
Power on, back light is OK, but nothing displayed on the screen or display is not clear	Display contrast problem	Adjust the contrast potentiometer
Measurements inaccurate	Cuvettes were contaminated	Clean cuvettes
	Samples were contaminated	Improve samples
	Poor matching of the cuvettes	Improve the matching of the cuvettes
	Dark current error	Resample dark current

## Repair and Maintenance

### Daily maintenance

#### Check the compartment

After measurement, the cuvettes with sample solutions should be taken out of the compartment in good time, otherwise the volatilization of the solution may cause mould to form on the mirror. Users must pay attention to the corrosive sample and liquid which is easy to volatilize. Any solution remaining in the compartment should be wiped off immediately.

#### Surface clean

The cover of the instrument is painted. Please use a wet towel to wipe off the drips on the surface immediately. Organic solution must not be used to clean the cover. Please wipe off any dirt on the cover immediately.



## Clean the cuvettes

After every test or after a solution change, the cuvettes should be cleaned carefully, otherwise any remains on the surface will cause measuring errors.

## Check lamp

In Wavelength Scan mode, set the test parameters as follow:

Scan From: 500 nm

Scan To: 200 nm

Scan Step: 1 nm

Press numeric key 6, enter the amplifier of ADC as "0", and press the Enter key to start scanning energy.

After the scan is finished, press the function key Search, then press <, > to browse the energy value point to point. Check the energy of the wavelength 500 nm and 200 nm, and check the energy. You will need to replace the W lamp in the following two cases:

Energy <20 from 500 to 340 nm W lamp is damaged

Energy <5000 at 500 nm W lamp energy is too low

You will need to replace the D2 lamp in the following two cases:

Energy <20 from 339 to 200 nm D2 lamp is damaged

Energy <1000 at 500 nm D2 lamp energy is too low

## Spare Parts Replacement

### Replace the fuse



**Danger! Be sure to switch off the power and unplug the cord from the socket before replacement!**

#### 1. Tools preparation


Prepare a 3×75 Flat Blade screwdriver.

#### 2. Switch off the power supply

Switch off the power supply and unplug the socket.


#### 3. Take out the fuse seat

Take out the fuse seat using a screwdriver.



#### 4. Replace the fuse

Take the new fuse (3.15 A/250 V) and place it into the working position.



**5. Reset the fuse seat**

Replace the fuse seat in the power socket.

**6. Switch on the power**

Plug the cord into the socket and switch on the power.

**Replace lamps**



**Hot ! Wait 20 minutes before opening the lamp chamber after power off to avoid scalding!**

**1. Tools preparation**

Prepare a 6×150 mm cross blade screwdriver and a pair of gloves.

**2. Power off**

Switch off the power supply and unplug the cord from the socket.


**3. Open the cover**

Unscrew the 4 screws indicated (2 screws on each side) and remove the cover.




**4. Open the cover of the light chamber**

Unscrew the 2 screws on the light chamber cover and remove it.



## 5. Replace the D2 lamp


Unscrew the 2 screws on the D2 Flange (No.1), unplug the connector in the power board (No.2) and remove the D2 lamp. Wearing a cotton glove, remove and replace the lamp bulb. Fix the 2 screws and plug in the connector again.



## 6. Replace W lamp


***The tungsten lamp is equipped with a blue-grey silicon coating by manufacturer. This coating is only a transport safety device. It can be removed with the first change of lamp bulb.***

Pull out the defective W lamp using a cotton glove. Insert the new W lamp as deep as possible on the lamp seat. Be sure to keep the filament in the same direction as the previous one faced.



## 7. Adjust the position of the W lamp

Switch on the power (the switch mirror should be placed to the position as indicated). Observe the entrance facular: it should be in the centre of the entrance hole. If the facular deviates to the left or right, loosen the No.1 screws in Fig. 5-8 and move the lamp seat to the left or right until it is flush with the centre of the slot. Then fix the screws. If the facular deviates up or down, loosen the No.2 screws and move the lamp seat up or down until the facular is flush with the centre of the slot. Then fix the No.2 screws again.



## 8. Finish

Reset the cover of the light chamber and fix the screws. Reset the cover of the instrument and fix the screws. Finally, recover the pole in the compartment.

### Replace the battery



**Be sure to switch off the power supply and unplug the cord from the socket before opening the bottom cover !**

#### 1. Prepare the tools

Prepare a 6×150mm cross blade screwdriver.

#### 2. Switch off the power supply

Switch off the power supply and unplug the cord from the socket


#### 3. Open the bottom cover plate

Unscrew all the screws indicated then remove the bottom plate.



#### 4. Replace the battery

Remove the old battery and replace it with a new one.



#### 5. Finish

Reattach the bottom plate and fix all the screws.

## Accessories and Spare Parts

Description	Quantity	Cat. No.
CELL HOLDER, 4-CELL, 10 MM	1PC	634-6057
CELL HOLDER, 4-CELL, 10 TO 50 MM	1PC	634-6045
CELL HOLDER, 4-CELL, 10 TO 100 MM	1PC	634-6046
CELL HOLDER, 1-CELL, 100 MM	1PC	634-6047
CELL HOLDER, FOR CYLINDRICAL CELL	1PC	634-6048
CELL HOLDER, WATER-JACKETED, 1 CELL, 10 MM	1PC	634-6049
CELL HOLDER, WATER-JACKED, 4 CELL, 10 MM	1PC	634-6050
CELL HOLDER FOR TEST TUBES	1PC	634-6051
CELL HOLDER, SOLID SAMPLE	1PC	634-6052
CELL HOLDER FOR MICRO CELLS, BEAM HEIGHT: 15 MM	1PC	634-6062

CELL HOLDER, 8-POSITION AUTO CELL CHANGER	1PC	634-6064
CUVETTE, SQUARE. GLASS, 10 MM	4PCS	634-6013
CUVETTE, SQUARE. GLASS, 20 MM	2PCS	634-6014
CUVETTE, SQUARE. GLASS, 30 MM	2PCS	634-6015
CUVETTE, SQUARE. GLASS, 50 MM	2PCS	634-6016
CUVETTE, SQUARE. GLASS, 100 MM	1PC	634-6017
CUVETTE, SQUARE. QUARTZ, 10 MM	2PCS	634-6018
CUVETTE, SQUARE. QUARTZ, 20 MM	2PCS	634-6019
CUVETTE, SQUARE. QUARTZ, 30 MM	2PCS	634-6020
CUVETTE, SQUARE. QUARTZ, 50 MM	2PCS	634-6021
CUVETTE, SQUARE. QUARTZ, 100 MM	1PC	634-6022
CELL, QUARTZ, 100 UL, 10 MM, BEAM HEIGHT: 15 MM	1PC	634-0688
CELL, QUARTZ, 200 UL, 10 MM, BEAM HEIGHT: 15 MM	1PC	634-0689
CELL, QUARTZ, 500 UL, 10 MM	1PC	634-6025
FLOW CELL, 5 MM, GLASS, BEAM HEIGHT: 15 MM	1PC	634-0690
FLOW CELL, 10 MM, GLASS, BEAM HEIGHT: 15 MM	1PC	634-0691
FLOW CELL, 20 MM, GLASS, BEAM HEIGHT: 15 MM	1PC	634-0692
FLOW CELL, 30 MM, GLASS, BEAM HEIGHT: 15 MM	1PC	634-0693
FLOW CELL, 5 MM, QUARTZ, BEAM HEIGHT: 15 MM	1PC	634-0694
FLOW CELL, 10 MM, QUARTZ, BEAM HEIGHT: 15 MM	1PC	634-0695
FLOW CELL, 20 MM, QUARTZ, BEAM HEIGHT: 15 MM	1PC	634-0696
FLOW CELL, 30 MM, QUARTZ, BEAM HEIGHT: 15 MM	1PC	634-0697
PELTIER UNIT, BEAM HEIGHT: 15 MM	1PC	634-6069
SIPPER UNIT WITHOUT TEMP. CONTROL, BEAM HEIGHT: 15 MM	1PC	634-6070
SIPPER UNIT WITH PELTIER TEMP. CONTROL, BEAM HEIGHT: 15 MM	1PC	634-6071
LAMP, HALOGEN, 12 V/20 W	1PC	634-0776
LAMP, DEUTERIUM	1PC	634-6038
PRINTER, THERMAL PRINTER	1PC	634-6039
DUST COVER	1PC	634-6044
FUSE, 3.15 A/250 V	1PC	634-0651
FUSE, 500 MA/250 V	1PC	634-0652
BATTERY, 3 V, CR2032	1PC	634-0653

# Part 2: Software

## Functions

This section introduces the functions of the UV-Vis Analyst.

### Main Functions

#### Single wavelength photometric measurement

- Go to a desired wavelength quickly and conveniently.
- Photometric value display mode can be changed (%Transmittance or Absorbance).

#### Fixed points measurement

##### Multi-wavelength photometric measurement

- Up to 20 wavelength points can be set.
- Results will be grouped into a table format automatically.

##### Concentration measurement

- 2 methods to set the regression curve.  
Up to 20 standards to set the regression curve. The UV-Vis Analyst will calculate the working curve using a linear equation that fits the data. Enter factor values to generate regression curve.
- 3 methods for curve fit.  
Linear fit, quadratic fit and cubic fit.

#### Wavelength scanning

- Allows user to set scan step (0.1, 0.2, 0.5, 1.0 and 5.0 nm).
- Spectrum display mode can be changed (Wavelength-%Transmittance or Wavelength-Absorbance).
- Peaks and valleys will be automatically detected after scanning (user can define the peak threshold).
- Powerful spectrum processing functions are provided.

#### Time scanning

- Allows user to set scan interval (0.5, 1.0, 2.0, 5.0, 10, 30 and 60 s).
- Spectrum display mode can be changed (Time-%Transmittance or Time-Absorbance).
- Peaks and valleys will be automatically detected after scanning (user can define the peak threshold).
- Powerful spectrum processing functions are provided.

#### DNA/Protein measurement

- Wavelength points and ratios can be set up.
- Results will be grouped into a table format automatically.

## **Spectrum processing function**

### **Trace a spectrum**

The cursor can be moved to a desired point in the spectrum displayed on the screen and the photometric data at this point is displayed.

### **Automatic peak detection**

After scanning is complete, peaks and valleys can be automatically detected and listed in a table format. They will also be labelled on the spectrum.

### **Scale expansion**

Simultaneous expansion of the X and Y axes are provided with the Zoom function. Display range can also be changed through the Display Setup function.

### **Differentiation**

You can calculate and display the first up to the fourth derivative spectrum for a given spectrum. Derivative spectrum is useful for enhancing spectrum data that are not readily apparent in an absorbance spectrum.

### **Calculate spectrum**

You can calculate addition, subtraction, multiplication and division between two spectra with the resulting data displayed on the screen.

## **System check and calibration function**

### **Instrument validity check**

Up to 10 wavelength points can be set in the instrument validity mode. Two methods can be selected (Photometric Validity measurement and Wavelength Validity measurement) and tolerance can be entered. Results will be grouped into a table format automatically.

### **Dark current check**

You can resample the dark current of the instrument.

### **Spectrum bandwidth check**

A special scan for checking spectrum bandwidth that will calculate the spectrum bandwidth value automatically.

### **Energy of light sources check**

Allows the user to scan the energy of light sources with a fixed gain (0–7).

### **Reset wavelength**

Allows the user to relocate the wavelength 656.1 nm.



# Installation


This section describes how to set up the UV-Vis Analyst to PC.

## PC system requirements


- Pentium or above PC;
- CD-ROM;
- USB Ports.
- 512 MB memory (1 GB or above is strongly recommended);
- 50 MB or above hard disk space;
- Microsoft Windows XP/Vista/7/8.

## Install UV-Vis Analyst


1. Put UV-Vis Analyst disc in the CD-ROM;
2. Double-click to open the CD-ROM, then double-click **Setup.exe** under the root directory of the CD to start installation. Click **Next**;




3. Choose install path, then click **Next** to copy files to PC;




4. After all files of UV-Vis Analyst have been copied, it will start to install the USB drive. Click **Next**;




5. Select "I accept this agreement". Click **Next** to copy files to PC;



6. Click **Finish** to finish installation of the USB drive;



7. Click **Finish** to complete the setup.



## Uninstall UV-Vis Analyst

Start → All Programs → UV-Vis Analyst → Uninstall **UV-Vis Analyst** to remove.


## Run UV-Vis Analyst

*Before you run UV-Vis Analyst, please check the following:*

- **Computer is connected to spectrophotometer using the USB cable;**
- **Spectrophotometer is on main interface.**




There are two ways to start the UV-Vis Analyst:

- Double-click shortcut icon  on the desktop.
- Start → All Programs → UV-Vis Analyst → **UV-Vis Analyst**.

## Set up communication port

Start the **UV-Vis Analyst**, then on the **UV-Photometer** menu, click **Comm. Port Setup** to bring up the following box; select the Comm. Port and Baud Rate (38400), and click **OK**.




# Introduction

We will introduce the UV-Vis Analyst in this chapter.

## Main Interface

This is the main interface after starting.























## Menu bar and toolbar












**Menu bar** and **toolbar** are both provided in the software offering you two ways to select a desired function.









- On the menu bar, use your keypad or mouse to select the desired function.
- Almost all the functions listed in the menu bar can be reached by clicking a corresponding button in the toolbar.

Main Menu	Sub Menu	Tool	Function
File	New		New fixed points measurement
			New wavelength scan measurement
			New time scan measurement
			New DNA/protein measurement

			New instrument validity
	Open...		Open a spectrum/data file
	Close		Close current measurement
	Save		Save current measurement
	Save As...		Save current measurement with a new file name
	Open file from UV-Photometer		Open a file saved in instrument
	Export		Export data or method
	Print...		Print test report
	Print Setup...		Set up printer
	Exit		Exit UV-Vis analyst
View	Status Bar		Display/hide status bar
	Status of Spectrophotometer		Display status of spectrophotometer
	Status font		Set up font of status bar
	Customize		Define the information of display and print
	Peaks		Mark peak value
	Valleys		Mark valley value
	Magnify		Magnify the area selected
	Restore		Restore the default parameters of display
	Search		Search peak/valley one by one

UV-Photometer	Link Spectrophotometer		Connect to the instrument
	Reset Spectrophotometer		Reset parameters of instrument
	Escape		Stop current measurement
	View Dark Current		Retest the dark current
	Set Amplifier		Reset amplifier
	Locate 656.1 nm		Relocate 656.1 nm
	Calibrate System Baseline		Scan system baseline
	Automatic Blank Calibration		Carry out the blank
	Slit Bandwidth *		Set slit bandwidth (0.5, 1, 2, 4, 5)
	Set Unit		Set unit
	Turn on/off W lamp		Turn on/off W lamp
	Turn on/off D2 lamp		Turn on/off D2 lamp
	D2/W Switch Point		Set switch point of D2/W
	Comm. Port Setup		Set up comm. port
	Change Password		Set/change login password
Auto-sample	Locate Cell **		Locate cell (1–8) to light path
	Setup Multicell **		Set up multicell
	Autorun **		Measure multi samples automatically
Scan	Start		Start a measurement

	Stop		Stop a measurement
	Service		Measure spectrum and scan energy
Settings	Display Range		Set up scan display parameters
	Peak Height		Define peak/valley threshold
Compute	Add		Add two spectra
	Sub		Subtract one spectrum from another
	Multiply		Multiply two spectra
	Divide		Divide one spectrum from another
	Moving Window Averaging		Smooth a spectrum with the moving window averaging method
	Savitzky-Golay Smoothing Filter		Smooth a spectrum with the Savitzky-Golay smoothing filter
	Derivate		Derivative of a spectrum
	Resample		Resample a spectrum
Window	New Window		New measurement window as current
	Cascade		Multi windows display in a cascade
	Tile		Multi windows display in tiled form
	Arrange Icons		Arrange all icons minimized
	Split		Split display area
Help	About UV-Vis Analyst		Display information about UV-Vis Analyst
			Set up measurement parameters

			Modify a measurement result
			Delete results selected
			Set and go to one wavelength
			Display instrument CPU information
			Delete current spectrum
			Display result as mode %T
			Display result as mode Abs
			Undo scale


**Note:** \* Only for the model with Variable Slit  
 \*\* Only for the model with 8-Cell Auto Charger


## Operation

This chapter describes how to use UV-Vis Analyst.

### Single wavelength photometric measurement

The UV-Vis Analyst provides a convenient method to measure photometric value at a fixed wavelength.

1. Click  on the toolbar to display **Goto specified wavelength**.



2. Enter the desired wavelength position, click **Goto**. The minimum wavelength step is 0.1 nm in a range 190–1100 nm.




- Place a sample in the sample compartment and a reference in the reference compartment. The wavelength position and photometric value will be displayed in the **Readout** box.

## Fixed point measurement

This UV-Vis Analyst performs fixed wavelength measurement at 1–20 points and defines how to analyse unknown compounds against calibration standards.

## Multi-wavelength photometric measurement

- Click  on the toolbar to display the following form.



The screenshot shows the UV-Vis Analyst software interface with the **Method** tab selected. The interface includes a menu bar (File, View, UV-Photometer, Auto-Sample, Window, Help), a toolbar, and a main workspace. The **Method** tab contains the following controls:

- Number of WL points:** A dropdown menu set to 10.
- Calculate Concentration:** A checked checkbox.
- Use Standard Samples:** An unchecked checkbox.
- Curve Fit:** A dropdown menu set to Linear Fit.
- Linear Fit coefficients:**
  - K0: 1.01301
  - K1: 1.10262
  - K2: 0
  - K3: 0
- Equation display:**


$$\Delta A = A_2 - A_1 = \frac{m \cdot A_1 + n \cdot A_2}{m + n}$$


$$m = A_3 - A_1 \quad n = A_2 - A_1$$
- Wavelength list:** A table with 20 rows (WL 1 to WL 20) and two columns for wavelength values.


WL 1	500
WL 2	510
WL 3	520
WL 4	530
WL 5	540
WL 6	510
WL 7	520
WL 8	530
WL 9	540
WL 10	550
WL 11	360
WL 12	370
WL 13	380
WL 14	390
WL 15	400
WL 16	410
WL 17	420
WL 18	430
WL 19	440
WL 20	450

The status bar at the bottom shows: Ready, Pos: 500.0nm, Abs: 0.003, S: 25825, R: 25997, CPU: 100. The taskbar at the bottom shows the Start button and open windows for UV-Vis Analyst and Notepad.


- Click the **Method** tab.
- Enter the number of wavelength points in the **Number of WL Points** box, or click the **up/down** arrows next to the box set the wavelength points. Leave the two boxes **Calculate Concentration** and **Use Standard Samples**.
- Enter the wavelength in the **Wavelength** box.
- Place a reference in the reference compartment.
- Click the **Sample** tab. It will display the following. The control menu contains six buttons: **Start**, **Delete**, **Modify**, **Recalculate**, **Data Font** and **Print**.



7. Place a sample in the sample compartment. Click **Start** or  to run a new measurement. The display will change to the following. Enter the sample name in the **Name** box.




8. Click **OK**. The photometric data for sample will be listed in the **Sample** table.
9. Repeat steps 7 and 8 to measure all samples.



## Concentration measurement

### Set up linear regression curve


There are two methods available to set up the linear regression curve. You can use standards to set up the regression curve or just enter the parameters manually. Use the following steps to select the method you wish to use.

1. Click  on the toolbar.
2. Click the **Method** tab.
3. Enter the number of wavelength points in the **Number of Points** box, or click the **up/down** arrow next to this box. With two wavelengths, the absorbance at the second reference wavelength is subtracted from the first to correct for background absorbance. With three wavelengths, the baseline between the first and third wavelengths is calculated and its value at the second wavelength is subtracted from the absorbance at the second wavelength to give the peak height.
4. Enter the wavelengths in the **Wavelength** boxes.
5. Tick the **Calculate Concentration** tick box to activate concentration calculation.
6. Set up the linear regression curve.

#### **Method 1: Set up the linear regression curve with prepared standards.**

- (1) Tick the **Use Standard Samples** tick box.
- (2) Place the reference into the reference holder.
- (3) Click the **Standard** tab.
- (4) Place Standard 1 in the sample compartment. Click **Start** to run a measurement.
- (5) Enter the concentration value of Standard 1 in the **Conc.** box.
- (6) Enter the sample name for the standard in the **Name** box.
- (7) Click **OK**. The photometric data,  $\Delta A$  and concentration will be shown in the standard table.

(8) Repeat steps 4–7 to measure all the prepared standards.





(9) Click **down arrow** in **Curve Fit** box to select curve fit method.

**Method 2: Input the factor of the linear regression curve.**

- (1) Leave the **Use Standard Samples** tick box unticked.
- (2) Click **down arrow** in **Curve Fit** box to select curve fit method.
- (3) Input the factor of the linear regression curve.


7. Click **Fitting** tab to view the **linear regression curve**. Click **Display Setting** tab to set the display parameters and unit of concentration.






### **Measure concentration by using the linear regression curve**

The following procedure describes how to measure concentration of samples.


1. Set up linear regression curve or click  to open a file of linear regression curve (\*.QUA).
2. Place reference into the reference holder.
3. Click the **Sample** tab.
4. Place Sample 1 into the sample holder.
5. Click **Start** to run a measurement.
6. UV-Vis Application software will display the photometric value of Sample 1 at the fixed wavelength positions automatically. Enter the sample name in the **Name** box. The default is **Sample-1**.
7. Click **OK**. The photometric result for Sample-1 will be listed in the sample data. Delta Abs. and concentration value of Sample-1 will also be displayed in columns 3 and 4.
8. Repeat steps 4–7 to measure remaining samples.





## Wavelength Scanning


This chapter describes how to collect a spectrum while using Wavelength Scan function.

### Scan sample

1. Click  on the toolbar to new a sample scan measurement to display the following form.




2. Click  on the toolbar to display the following form. Input start wavelength in **From** box (range: 190–1100 nm), end wavelength in **To** box (range: 190–1100 nm), select scan interval (0.1, 0.2, 0.5, 1.0, 2.0 or 5.0 nm) and filter times (5, 10, 30 or 50), click **OK**.




3. Click  on the toolbar to select %Transmittance mode or click  to select Absorbance mode.


4. Click  on the toolbar to set display parameters.






5. Place reference into the reference holder.



6. Place sample into the sample holder. Click  to scan sample, the real time spectrum will be

displayed. Click  to cancel while scanning.




## Auto list peaks and valleys

Click  on the toolbar to set the peak/Valley threshold (range: 0 to 1.000, step: 0.001), input the threshold value, click **OK**. Click  to list peaks and click  to list valleys.




## Rescale



Click  on the toolbar to set the new parameters for display.

## Original scales



Click  on the toolbar to restore the default display settings.

## Zoom selected area


Click  on the toolbar to activate zoom function. Position the cursor in the upper-left corner of the area you want to select. Hold the left mouse button to drag the cursor to outline the spectrum area you want to enlarge. Release the mouse button. The part of the spectrum which is displayed within the outlined area will


be enlarged. Click  to undo scale. To cancel zoom to click  again.






## Trace a spectrum

Click  on the toolbar, a crosshair cursor appears, move the cursor on the spectrum. Move the crosshair cursor left or right on the spectrum. The data in the cursor window indicate the X-axis and Y-axis values for the current cursor location. Press ESC key to release the crosshair cursor.




## Select a spectrum as current


As UV-Vis Application software can display several spectra overlaid on the screen, you should specify the spectrum you wish to process. Click the **down** arrow on the toolbar. All spectra will be listed in the drop-down menu. Click the spectrum you want to select. Its name will be listed in the Name Box and it will be referred to as **Current Spectrum**.




## Derivative



Click  on the toolbar. The following dialogue box appears. Enter the class of derivative (1–10, depending on whether first, second, ... tenth derivative is required) and a name for the result spectrum, then click **OK**. The result spectrum will be displayed overlaid with the original one.



#### 4.3.2.1 Moving window averaging

Click  on the toolbar. The following dialogue box will be displayed. Click **up/down** arrow of the **Range** box to select range value, enter a file name in the **Name** box, click **OK**. The result spectrum will be displayed overlaid with the original one.

Smooth the spectrum

Smooth


Range

Name

Sample-2-s



OK

Cancel





## Savitzky-Golay Smoothing Filter


On the **Computer** menu, click **Savitzky-Golay Smoothing Filter**. The following dialogue box will be displayed. Click **up/down** arrow to select the parameters, enter a file name in the Name of Result box, click **OK**. The result spectrum will be displayed overlaid with the original one.



## Resample


Click  on the toolbar. The following dialogue box will be displayed. Click **Up/Down** arrow to select Sample times. Click **OK**. The new spectrum is displayed.





## Spectrum addition


Spectrum addition can assist in the development of artificial spectrum in multi-component mixtures.

Click  on the toolbar. The following dialogue box will be displayed. Click the **down** arrow next to **File 1** to select a spectrum and define it as source 1. Select a spectrum for **File 2** in the same way. It will not allow you to select the same spectrum twice. Enter a name for the **Result** spectrum and click **OK**. The result spectrum will be displayed on the screen.




UV-Vis Analyst will only add, subtract, multiply and divide two spectra that are already displayed on the screen. Before arithmetic processing, load or collect two spectra from memory.


The screenshot shows the 'Spectra Addition/Subtraction' dialog box. It has a title bar with a close button. Inside, there are three rows of controls. The first row is for 'File 1' with a dropdown menu showing 'C:\Documents and Settings\Mark...'. The second row is for 'File 2' with a similar dropdown menu. Between these two rows are four radio buttons labeled '+', '-', 'x', and '/'. The third row is for 'Result' with a text input field containing 'ResultName'. On the right side of the dialog are 'OK' and 'Cancel' buttons.




## Spectrum subtraction

Subtracting one spectrum from another is a classic technique to offset spectrum interference from the spectrum of interest.


Click  on the toolbar. The following dialogue box will be displayed. Click the **down** arrow next to **File 1** to select a spectrum and define it as source 1. Select a spectrum for **File 2** in the same way. It will not allow you to select the same spectrum twice. Enter a name for the **Result** spectrum and click **OK**. The result spectrum will be displayed on the screen.






## Spectrum multiplication

Multiplying spectra can assist in the development of artificial structure of a spectrum in multi-component mixtures.

Click  on the toolbar. The following dialogue box will be displayed. Click the **down** arrow next to **File 1** to select a spectrum and define it as source 1. Select a spectrum for **File 2** in the same way. It will not allow you to select the same spectrum twice. Enter a name for the **Result** spectrum and click **OK**. The result spectrum will be displayed on the screen.

The screenshot shows the 'Spectra Addition/Subtraction' dialog box. It has a title bar with a close button. Inside, there are three rows of controls. The first row is for 'File 1', the second for 'File 2', and the third for 'Result'. Each row has a dropdown menu and a text input field. Below the dropdowns are four buttons: '+', '-', 'x', and '/'. To the right of the dialog are 'OK' and 'Cancel' buttons.






## Spectrum division


Dividing one spectrum from another is a classic technique to offset spectrum interference from the spectrum of interest.



Click  on the toolbar. The following dialogue box will be displayed. Click the **down** arrow next to **File 1** to select a spectrum and define it as source 1. Select a spectrum for **File 2** in the same way. It will not allow you to select the same spectrum twice. Enter a name for the **Result** spectrum and click **OK**. The result spectrum will be displayed on the screen.

The screenshot shows the 'Spectra Addition/Subtraction' dialog box. It has a title bar with a close button. Inside, there are three rows: 'File 1', 'File 2', and 'Result'. Each row has a dropdown menu. The 'File 1' dropdown is currently set to 'C:\Documents and Settings\Mark...'. Below the dropdowns are four radio buttons: '+', '-', 'x', and '/'. The 'Result' row has a text input field containing 'ResultName'. On the right side of the dialog are 'OK' and 'Cancel' buttons.





## Unload a spectrum

Select the spectrum you want to unload as the **Current Spectrum**, Click  on the toolbar to remove the spectrum from the display.


## Define display information

Click  on the toolbar to display the **Settings to display and print the spectra** form, click the **Legend** tab, enter the information for display.

The dialog box 'Settings to display and print the spectra' has several tabs: View, Peak and Valley, Legend, Special, Scaler, Print, and Memo. The 'Legend' tab is selected. It contains fields for X-Axis (set to 'W'), Y-Axis (set to 'abs', with 'Abs' and 'trans' as options), and Title (set to 'Sample-2'). Each field has a 'Font' button next to it. At the bottom are 'OK', 'Cancel', 'Apply', and 'Help' buttons.

## Edit print information


Click  on the toolbar to display the **Settings to display and print the spectra** form, click the **Print** tab, enter the information for printout.







## Time Scanning (Kinetic Analysis)


This chapter describes how to obtain the absorbance or transmittance value for a sample as a function of time at a given wavelength.



### Scan sample


1. Click  on the toolbar, the following dialogue box will appear.




2. Click  on the toolbar to select the %transmittance mode or click  to select the absorbance mode.
3. Click  on the toolbar. The following dialogue box will be displayed. Key in the wavelength, total time (in seconds) and scan step in the dialogue box. The wavelength range should be within 190 to 1100 nm. The upper limit for total time is 100000 s. Seven scan intervals can be selected from 0.5S, 1S, 2S, 5S, 10S, 30S and 60S. Click **OK**.




4. Place a reference in the reference holder.
5. Take out the blank in the sample holder, place a sample in it and close the cover.
6. Place a sample in the sample holder. Click  on the toolbar. The instrument will start scanning automatically. The graph will be displayed on the screen during time scanning. You can stop scanning by clicking  .




## Calculate rate

Click  on the toolbar to display the **Settings to display and print the spectra** form, click the **Dynamic Analysis** tab, enter the start time in **Time Begin** box, enter the end time in **Time End** box, and enter the K factor in **K Factor** box, click **Calculate**, the result will be displayed.




## Define display information

Click  on the toolbar to display the **Settings to display and print the spectra** form, click the **Legend** tab, enter the information for display.



## Edit print information


Click  on the toolbar to display the **Settings to display and print the spectra** form, click the **Legend** tab, enter the information for display.




## DNA/Protein Measurement


This chapter describes how to perform DNA/Protein measurement.


### DNA/protein measurement


1. Click  on the toolbar, the following dialogue box will appear.




- Click the **down** arrows of the **method** to select the **test method**. Enter the wavelength position in the **Wavelength** box. Enter the value of **DNA/Protein Conc.**
- Place a reference in the reference holder.
- Click the **Sample** tab. It will display the following. The control menu contains six buttons: **Start**, **Delete**, **Modify**, **Recalculate**, **Font** and **Print**.



- Place a sample in the sample holder. Click **Start** or  to run a new measurement. The display will change to the following.



- The UV-Vis Analyst will read the photometric value of **sample 1** at the fixed wavelength automatically. Enter the sample name in the **Name** box. Click **OK** after the measurement is complete. The photometric data for **sample 1** will be listed in the sample table.
- Repeat steps 5 and 6 to test all samples.



# Appendix 1

## Methods of Quantitative Analysis

Single Wavelength Method :  $Abs.=A_1$

Double Wavelengths Method :  $Abs.=m \cdot A_1 - n \cdot A_2$

Three Wavelengths Method :  $Abs.=A_1 - (W_1 - W_2) \cdot (A_2 - A_3) / (W_2 - W_3) - A_3$

## Technical service

### Web Resources

Visit the VWR website at [www.vwr.com](http://www.vwr.com) for:

- Complete technical service contact information
- Access to the VWR Online Catalogue, and information about accessories and related products
- Additional product information and special offers

**Contact us** For information or technical assistance contact your local VWR representative or visit.

[www.vwr.com](http://www.vwr.com).

## Warranty

**VWR International** warrants that this product will be free from defects in material and workmanship for a period of two (2) years from date of delivery. If a defect is present, VWR will, at its option and cost, repair, replace, or refund the purchase price of this product to the customer, provided it is returned during the warranty period. This warranty does not apply if the product has been damaged by accident, abuse, misuse, or misapplication, or from ordinary wear and tear. If the required maintenance and inspection services are not performed according to the manuals and any local regulations, such warranty turns invalid, except to the extent, the defect of the product is not due to such non-performance.

Items being returned must be insured by the customer against possible damage or loss. This warranty shall be limited to the aforementioned remedies. IT IS EXPRESSLY AGREED THAT THIS WARRANTY WILL BE IN LIEU OF ALL WARRANTIES OF FITNESS AND IN LIEU OF THE WARRANTY OF MERCHANTABILITY.

## Compliance with local laws and regulations

The customer is responsible for applying for and obtaining the necessary regulatory approvals or other authorisations necessary to run or use the Product in its local environment. VWR will not be held liable for any related omission or for not obtaining the required approval or authorisation, unless any refusal is due to a defect of the product.



## Equipment disposal



This equipment is marked with the crossed out wheeled bin symbol to indicate that this equipment must not be disposed of with unsorted waste.

Instead it's your responsibility to correctly dispose of your equipment at lifecycle -end by handling it over to an authorized facility for separate collection and recycling. It's also your responsibility to decontaminate the equipment in case of biological, chemical and/or radiological contamination, so as to protect from health hazards the persons involved in the disposal and recycling of the equipment.

For more information about where you can drop off your waste of equipment, please contact your local dealer from whom you originally purchased this equipment.

By doing so, you will help to conserve natural and environmental resources and you will ensure that your equipment is recycled in a manner that protects human health.

Thank you

## Your Distributor

### Australia

VWR International Pty.LTD  
Unit 1/31 Archimedes Place  
Murarrie  
QLD 4172 Australia  
Tel.: 1300 727 696

### Austria

VWR International GmbH  
Graumannsgasse 7  
1150 Vienna  
Tel.: +43 1 97 002 0  
Email: info@at.vwr.com

### Belgium

VWR International bvba  
Researchpark Haasrode 2020  
Geldenaaksebaan 464  
3001 Leuven  
Tel.: 016 385 011  
Email: vwrbe@be.vwr.com

### China

VWR International China Co., Ltd  
2nd Floor, Building 4,  
Lane 998, Halei Rd,  
Zhangjiang Hi-tech Park  
Shanghai, 201203  
Tel.: +86-21 589 868 88  
Email: info\_china@vwr.com

### Czech Republic

VWR International s. r. o.  
Veetee Business Park  
Pražská 442  
CZ - 281 67 Stříbrná Skalice  
Tel.: +420 321 570 321  
info@cz.vwr.com

### Denmark

VWR - Bie & Berntsen  
Transformervej 8  
2730 Herlev  
Tel.: 43 86 87 88  
Email: info@dk.vwr.com

### Finland

VWR International Oy  
Valimotie 9  
00380 Helsinki  
Tel.: 09 80 45 51  
Email: info@fi.vwr.com

### France

VWR International S.A.S.  
Le Périgares – Bâtiment B  
201, rue Carnot  
94126 Fontenay-sous-Bois cedex  
Tel.: 0 825 02 30 30 (0,15 EUR TTC/min)  
Email: info@fr.vwr.com

### Germany

VWR International GmbH  
Hilpertstraße 20a  
D - 64295 Darmstadt  
Freecall: 0800 702 00 07  
Email: info@de.vwr.com

### Hungary

VWR International Kft.  
Simon László u. 4.  
4034 Debrecen  
Tel.: (52) 521-130  
Email: info@hu.vwr.com

### India

VWR Lab Products Private Limited  
135/12, Brigade Towers, 2nd Floor  
Front wing, Brigade Road,  
Bengaluru, India – 560 025  
Tel.: +91-80-41117125/26 (Bengaluru)  
Tel.: +91-2522-647911/922 (Mumbai)  
Email: vwr\_india@vwr.com

### Ireland / Northern Ireland

VWR International Ltd / VWR  
International (Northern Ireland) Ltd  
Orion Business Campus  
Northwest Business Park  
Ballycoolin  
Dublin 15  
Tel.: 01 88 22 222  
Email sales@ie.vwr.com

### Italy

VWR International PBI S.r.l.  
Via San Giusto 85  
20153 Milano (MI)  
Tel.: 02-3320311/02-487791  
Email: info@it.vwr.com

### The Netherlands

VWR International B.V.  
Postbus 8198  
1005 AD Amsterdam  
Tel.: 020 4808 400  
Email: info@nl.vwr.com

### New Zealand

VWR International LP  
241 Bush Road  
Albany 0632, Auckland  
Tel.: 0800 734 100  
Email: sales@globalscience.co.nz

### Norway

VWR International AS  
Haavard Martinsens vei 30  
0978 Oslo  
Tel.: 02290  
Email: info@no.vwr.com

### Poland

VWR International Sp. z o.o.  
Limbowa 5  
80-175 Gdansk  
Tel.: 058 32 38 210  
Email: labart@pl.vwr.com

### Portugal

VWR International –  
Material de Laboratório, Lda  
Edifício Neopark  
Av. Tomás Ribeiro, 43- 3 D  
2790-221 Carnaxide  
Tel.: 21 3600 770  
Email: info@pt.vwr.com

### Singapore

VWR Singapore Pte Ltd  
18 Gul Drive  
Singapore 629468  
Tel: +65 6505 0760  
Email: sales@sg.vwr.com

### Spain

VWR International Eurolab S.L.  
C/ Tecnología 5-17  
A-7 Llinars Park  
08450 - Llinars del Vallès  
Barcelona  
Tel.: 902 222 897  
Email: info@es.vwr.com

### Sweden

VWR International AB  
Fagerstagatan 18a  
163 94 Stockholm  
Tel.: 08 621 34 00  
Email: info@se.vwr.com

### Switzerland

VWR International AG  
Lerzenstrasse 16/18  
8953 Dietikon  
Tel.: 044 745 13 13  
Email: info@ch.vwr.com

### Turkey

VWR International Laboratuvar  
Teknolojileri Ltd.Şti.  
Orta Mah. Cemal Gürsel Caddesi  
Ördekcioglu İşmerkezi No.32/1  
34896 Pendik - Istanbul  
Tel.: +90216 598 2900  
Email: info@pro-lab.com.tr

### UK

VWR International Ltd  
Customer Service Centre  
Hunter Boulevard  
Magna Park  
Lutterworth  
Leicestershire  
LE17 4XN  
Tel.: 0800 22 33 44  
Email: uksales@uk.vwr.com